




Insert threaded knob into threaded hole.

Place knee trough pole into bracket ensuring that the longest section is pointing down.



Connect knee trough to pole.

Firmly push the two together.



Finished item.

